



Replace Rear Primary Seals

SB-24-11-006

October 25, 2024

| Classification | | Section/Group | Mobile Service | Configuration |
|-----------------|------------|-----------------------|-------------------------------|---------------|
| Repair Bulletin | | 11 - Closures | Can Perform (where permitted) | All |
| Model | Model Year | Country/Region | Build Location | |
| Model Y | 2020-2024 | United States, Canada | Giga Texas, Fremont | |

The model(s) and model year(s) listed are a general approximation of the affected VIN list. Refer to the VIN/Bulletin Tracker or Customer/Vehicle profile to determine applicability of this bulletin for a particular vehicle.

This repair bulletin provides instructions on addressing a possible customer concern regarding the operation of Tesla vehicles. These instructions should only be performed by trained professionals.

Condition

On certain Model Y vehicles, the LH and/or RH rear primary body seals might cause wind noise in the cabin.

Correction

Upon customer complaint, or if replacing one rear primary body seal due to service outside of this bulletin, replace both seals with updated parts.



NOTE: Even if the condition is observed on only one seal, both seals must be replaced.

| Correction Description | Correction | Time |
|---|------------|------|
| SB-24-11-006 Not Applicable | S012411006 | 0.00 |
| Replace Both LH And RH Rear Primary Seals | S022411006 | 0.12 |

| Part Number | Description | Quantity |
|------------------------------------|-------------------------------------|----------|
| Parts Required 1497675-00-H | PRIMARY SEAL, BODY, REAR, LH/RH, MY | 2 |

This part number was current at the time of publication. Use the revision listed or later, unless otherwise specified in the [Parts Catalog](#).

Procedure

Replace both LH and RH rear primary seals (refer to Service Manual procedure [11700502](#)).