



Inspect Instrument Panel Decor Assembly

SB-24-14-002

December 10, 2024

| Classification | | Section/Group | Mobile Service | Configuration |
|-----------------|------------|--|-------------------------------|---------------|
| Repair Bulletin | | 14 - Instrument Panel | Can Perform (where permitted) | All |
| Model | Model Year | Country/Region | Build Location | |
| Model S | 2024 | North America, EMEA, Canada, China, Taiwan | Fremont | |

The model(s) and model year(s) listed are a general approximation of the affected VIN list. Refer to the VIN/Bulletin Tracker or Customer/Vehicle profile to determine applicability of this bulletin for a particular vehicle.

This repair bulletin provides instructions on addressing a possible customer concern regarding the operation of Tesla vehicles. These instructions should only be performed by trained professionals.

Condition

On some Model S vehicles, the wood grain and color harmony of the instrument panel (IP) decor assembly may not match that of the door trim.

Correction

Upon customer complaint, inspect the vehicle for symptoms related to the condition. If symptoms are present, replace the IP decor assembly.

| Correction Description | Correction | Time |
|---|------------|------|
| SB-24-14-002 Not Applicable | S012414002 | 0.00 |
| Inspect And Replace Instrument Panel Decor Assembly | S022414002 | 0.42 |

| Part Number | Description | Quantity |
|------------------------------------|---|----------|
| Parts Required 1562938-02-G | INSTRUMENT PANEL DECOR ASSEMBLY - LEFT HAND DRIVE - EBONY | 1 |

This part number was current at the time of publication. Use the revision listed or later, unless otherwise specified in the [Parts Catalog](#).

Procedure

Inspect the IP decor assembly for a mismatch in wood grain and color harmony compared to the door trim (Figure 1).




Figure 1 – Mismatch in wood grain and color harmony between door trim (left) and IP decor assembly (right)

- If a mismatch between the IP decor assembly and door trim wood grain and color is not present, no further action is required. Use correction code S012414002.
- If a mismatch between the IP decor assembly and door trim wood grain and color is present, replace the IP decor assembly with the updated part that matches the door trim (refer to Service Manual procedure [14057002](#)). Use correction code S022414002.